SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority ® Long Sleeve Twill Shirt. S600T

Product photo



Clean, crisp and versatile, our twill shirt has a professional appearance with comfortable, garment-washed softness.

- 5-ounce, 100% cotton
- Button-down collar
- Horn-tone buttons
- Left chest pocket
- Back box pleat
- Rounded adjustable cuffs

CARE INSTRUCTIONS

Machine wash cold with like colors. Do not bleach. Do not dry clean. Tumble dry low. Warm iron if necessary.

Sketches



front



back

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority ® Long Sleeve Twill Shirt. S600T

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL	5XL	6XL
Chest Width	20	21 1/2	23	24 1/2	26	27 1/2	29	30 1/2	35 1/2	37
Sleeve Length	31	32 1/2	34 1/2	35 1/2	37	38	39	40	41	42
Body Length at Back	27	29	31	31 1/2	33	33 1/2	34 1/2	35	35 1/2	36
Neck	16 1/2	16 1/2	17	17 1/2	18 1/2	19 1/4	20	20 3/4	21 1/2	22 1/4
Pocket Height	5 1/2	5 1/2	5 3/4	5 3/4	5 3/4	5 3/4	5 3/4	6	6	6
Pocket Width	5	5	5 1/4	5 1/4	5 1/4	5 1/4	5 1/4	5 1/2	5 1/2	5 1/2

Chest Width: Measured across the chest one inch below armhole when laid flat.

Sleeve Length: Start at center of neck and measure down shoulder, down sleeve to hem.

Body Length at Back: Measured from high point shoulder to finished hem at back.

Neck: Measured from center of button to center of buttonhole.

Pocket Height: Measure from top to bottom at center.

Pocket Width: Measure from side to side at top edge.

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority ® Long Sleeve Twill Shirt. S600T

SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL	5XL	6XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57	58-60	61-63
Neck	16 1/2	16 1/2	17	17 1/2	18 1/2	19 1/4	20	20 3/4	21 1/2	22 1/4
Arm	30 1/2	32	34	35	36 1/2	37 1/2	38 1/2	39 1/2	40 1/2	41 1/2
Pocket Height	5 1/2	5 1/2	5 3/4	5 3/4	5 3/4	5 3/4	5 3/4	6	6	6
Pocket Width	5	5	5 1/4	5 1/4	5 1/4	5 1/4	5 1/4	5 1/2	5 1/2	5 1/2

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority ® Long Sleeve Twill Shirt. S600T

HOW TO MEASURE

NECK

Measure around the fullest part of the neck at the base.

CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

NECK

Measure around the fullest part of the neck at the base.

CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

ARM

Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

NECK

Measure around the fullest part of the neck at the base.

CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

ARM

Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

NECK

Measure around the fullest part of the neck at the base.

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority ® Long Sleeve Twill Shirt. S600T



Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

COLORS

Black	Bright Burgundy	Classic Navy	Faded Olive	Khaki
BLACK C	194 C	433C	417 C	7530C