SPEC SHEET + MEASUREMENTS

Red Kap ® Long Sleeve Industrial Work Shirt. SP14

Product photo



Red Kap puts the toughest materials and advanced stay-clean technology into this shirt so you get the most out of it. This hardworking IL50 style is tested through 50 industrial launderer washes.

- 4.25-ounce, 65/35 poly/cotton with Touchtex™ technology which provides breathable comfort lasting colors and stain resistance
- Requires minimal ironing thanks to a wrinkle-resistant finish
- Open collar with sewn-in stays
- Separate two-piece yoke
- 6 button with metal collar gripper closure at neck
- Two button-through pockets
- Bartacked pencil stall on left pocket
- Industrial laundry friendly


CARE INSTRUCTIONS

Machine wash, tumble dry.

Sketches



front



back

SPEC SHEET + MEASUREMENTS

Red Kap ® Long Sleeve Industrial Work Shirt. SP14

PRODUCT MEASUREMENTS

	SR	MR	LR	XLR	2XLR	3XLR	4XLR	5XLR	6XLR
Body Length at Back	31 1/2	31 5/8	31 3/4	31 7/8	32	32 1/8	32 1/4	32 3/8	32 3/8
Chest Width	21	23	25	27	29	30 1/2	32	33 1/2	35
Sleeve Length from Center Back	33	33 1/2	34	34 1/2	35	35	35	35	35
Pocket Height	5 1/2	5 1/2	5 1/2	5 1/2	5 1/2	5 1/2	5 1/2	5 1/2	5 1/2
Pocket Width	5	5	5	5	5	5	5	5	5

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest Width: Measured across the chest one inch below armhole when laid flat.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

Pocket Height: Measure from top to bottom at center.

Pocket Width: Measure from side to side at top edge.

SPEC SHEET + MEASUREMENTS

Red Kap ® Long Sleeve Industrial Work Shirt. SP14

SIZE CHARTS

	SR	MR	LR	XLR	2XLR	3XLR	4XLR	5XLR	6XLR
Chest	34 1/2 - 38	38 1/2 -42	42 1/2 - 46	46 1/2 - 50	50 1/2 - 53	53 1/2 - 56	56 1/2 - 59	59 1/2 - 62	62 1/2 - 65
Neck	13 5/8 - 14 1/2	14 5/8 - 15 1/2	15 5/8 - 16 1/2	16 5/8 - 17 1/2	17 5/8 - 18 1/2	18 5/8 - 19 1/2	19 5/8 - 20 1/2	20 5/8 - 21 1/2	21 5/8 - 22 1/2
Arm	34.25	34.75	35.25	35.75	36.25	36.75	37.25	37.75	38

SPEC SHEET + MEASUREMENTS

Red Kap ® Long Sleeve Industrial Work Shirt. SP14

HOW TO MEASURE

NECK

Measure around the fullest part of the neck at the base.

CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

NECK

Measure around the fullest part of the neck at the base.

CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

ARM

Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

NECK

Measure around the fullest part of the neck at the base.

CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

ARM

Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

NECK

Measure around the fullest part of the neck at the base.

SPEC SHEET + MEASUREMENTS

Red Kap ® Long Sleeve Industrial Work Shirt. SP14



Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

COLORS

Black
BLACK C

Charcoal
7540C

Grey
409C

Light Blue
7451C

Light Green
5625 C

Light Grey
422C

Light Tan
7536C

Navy
532C

Petrol Blue
2135C