

SPEC SHEET + MEASUREMENTS



Red Kap® Long Size, Short Sleeve Striped Industrial Work Shirt. CS20LONG

Product photo



This hardworking IL50 style has a professional stripe and is tested through 50 industrial launderer washes.

- 4.25-ounce, 65/35 poly/cotton with Touchtex™ technology which provides breathable comfort lasting colors and stain resistance
- Requires minimal ironing thanks to a wrinkle-resistant finish
- Open collar with sewn-in stays
- Separate two-piece yoke
- 7 buttons including button at neck
- Two button-through pockets
- Bartacked pencil stall on left pocket
- Industrial laundry friendly

Sketches



front



back

CARE INSTRUCTIONS

Machine wash, tumble dry.

SPEC SHEET + MEASUREMENTS



Red Kap® Long Size, Short Sleeve Striped Industrial Work Shirt. CS20LONG

PRODUCT MEASUREMENTS

	ML	LL	XLL	2XLL	3XLL
Chest Width	23	25	27	29	30 1/2
Sleeve Length from Center Back	20 1/4	21 1/4	22 1/4	23	23 3/4
Neck	15 1/2	16 1/2	17 1/2	18 1/2	19 1/2
Body Length at Back	36 1/2	36 3/4	37	37 1/4	37 1/2
Pocket Width	5	5	5	5	5
Pocket Height	5 3/8	5 3/8	5 3/8	5 3/8	5 3/8

Chest Width: Measured across the chest one inch below armhole when laid flat.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

Neck: Measured from center of button to center of buttonhole.

Body Length at Back: Measured from high point shoulder to finished hem at back.

Pocket Width: Measure from side to side at top edge.

Pocket Height: Measure from top to bottom at center.

SPEC SHEET + MEASUREMENTS



Red Kap® Long Size, Short Sleeve Striped Industrial Work Shirt. CS20LONG

SIZE CHARTS

	ML	LL	XLL	2XLL	3XLL
Chest	38 1/2 - 42	42 1/2 - 46	46 1/2 - 50	50 1/2 - 53	53 1/2 - 56
Neck	14 5/8 - 15 1/2	15 5/8 - 16 1/2	16 5/8 - 17 1/2	17 5/8 - 18 1/2	18 5/8 - 19 1/2

HOW TO MEASURE

NECK

Measure around the fullest part of the neck at the base.

CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

NECK

Measure around the fullest part of the neck at the base.



NECK

Measure around the fullest part of the neck at the base.

CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

SPEC SHEET + MEASUREMENTS



Red Kap[®] Long Size, Short Sleeve Striped Industrial
Work Shirt. CS20LONG

COLORS



Grey/ Blue
2135C



Grey/ White
7540C



Petrol Blue/
Navy
7682C



White/ Blue
2135C