

SPEC SHEET + MEASUREMENTS



Red Kap® Long Size, Long Sleeve Industrial Work Shirt. SP14LONG

Product photo



Red Kap puts the toughest materials and advanced stay-clean technology into this shirt so you get the most out of it. This hardworking IL50 style is tested through 50 industrial launderer washes.

- 4.25-ounce, 65/35 poly/cotton with Touchtex™ technology which provides breathable comfort lasting colors and stain resistance
- Requires minimal ironing thanks to a wrinkle-resistant finish
- Open collar with sewn-in stays
- Separate two-piece yoke
- 6 buttons with metal collar gripper closure at neck
- Two button-through pockets
- Bartacked pencil stall on left pocket
- Industrial laundry friendly

Sketches



front



back

CARE INSTRUCTIONS

Machine wash, tumble dry.

SPEC SHEET + MEASUREMENTS



Red Kap® Long Size, Long Sleeve Industrial Work Shirt. SP14LONG

PRODUCT MEASUREMENTS

	ML	LL	XLL	2XLL	3XLL
Body Length at Back	33 7/8	34 1/8	34 3/8	34 5/8	34 7/8
Chest Width	46	50	54	57	60
Sleeve Length from Center Back	36 1/4	36 3/4	37 1/4	37 3/4	38 1/4

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest Width: Measured across the chest one inch below armhole when laid flat.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

SIZE CHARTS

	ML	LL	XLL	2XLL	3XLL
Chest	38 1/2 - 42	42 1/2 - 46	46 1/2 - 50	50 1/2 - 53	53 1/2 - 56
Neck	14 5/8 - 15 1/2	15 5/8 - 16 1/2	16 5/8 - 17 1/2	17 5/8 - 18 1/2	18 5/8 - 19 1/2
Arm	36.25	36.75	37.25	37.75	38.25

SPEC SHEET + MEASUREMENTS



Red Kap[®] Long Size, Long Sleeve Industrial Work Shirt.
SP14LONG

HOW TO MEASURE

NECK

Measure around the fullest part of the neck at the base.

CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

NECK

Measure around the fullest part of the neck at the base.

CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

ARM

Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

NECK

Measure around the fullest part of the neck at the base.

CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

ARM

Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

NECK

Measure around the fullest part of the neck at the base.

SPEC SHEET + MEASUREMENTS



Red Kap® Long Size, Long Sleeve Industrial Work Shirt. SP14LONG



Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

COLORS



Black
BLACK C



Charcoal
7540C



Grey
409C



Light Blue
652 C



Light Grey
422C



Light Tan
7536C



Navy
532C



Orange



Petrol Blue
2135C