

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY.

Port Authority® Tall Long Sleeve Twill Shirt. TLS600T

Product photo



Clean, crisp and versatile, our twill shirt has a professional appearance with comfortable, garment-washed softness.

- 5-ounce, 100% cotton
- Button-down collar
- Horn-tone buttons
- Left chest pocket
- Back box pleat
- Rounded adjustable cuffs

CARE INSTRUCTIONS

Machine wash cold with like colors. Do not bleach. Do not dry clean. Tumble dry low. Warm iron if necessary.

Sketches



front



back

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® Tall Long Sleeve Twill Shirt. TLS600T

PRODUCT MEASUREMENTS

	LT	XLT	2XLT	3XLT	4XLT
Chest Width	24 1/2	26	27 1/2	29	30 1/2
Sleeve Length	37	38 1/2	39 1/2	40 1/2	41 1/2
Neck	17	17 1/2	18	18 1/2	19
Body Length at Back	33 1/2	35	35 1/2	36 1/2	37
Pocket Height	5 3/4	5 3/4	5 3/4	5 3/4	6
Pocket Width	5 1/4	5 1/4	5 1/4	5 1/4	5 1/2

Chest Width: Measured across the chest one inch below armhole when laid flat.

Sleeve Length: Start at center of neck and measure down shoulder, down sleeve to hem.

Neck: Measured from center of button to center of buttonhole.

Body Length at Back: Measured from high point shoulder to finished hem at back.

Pocket Height: Measure from top to bottom at center.

Pocket Width: Measure from side to side at top edge.

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® Tall Long Sleeve Twill Shirt. TLS600T

SIZE CHARTS

	LT	XLT	2XLT	3XLT	4XLT
Chest	41-43	44-46	47-49	50-53	54-57
Neck	16 - 16 1/2	16 1/2 - 17	17 - 17 1/2	17 1/2 - 18	18 - 18 1/2
Arm	36 1/2	38	39	40	41

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® Tall Long Sleeve Twill Shirt. TLS600T

HOW TO MEASURE

NECK

Measure around the fullest part of the neck at the base.

CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

NECK

Measure around the fullest part of the neck at the base.

CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

ARM

Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

NECK

Measure around the fullest part of the neck at the base.

CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

ARM

Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

NECK

Measure around the fullest part of the neck at the base.

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® Tall Long Sleeve Twill Shirt. TLS600T



Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

COLORS



Black
BLACK C



Classic Navy
433C



Khaki
7530C